

Appendix C17.08

Section 1 Summary Field Survey Results

Section 1 – Summary Field Survey Results

Ref.	Type	Townland	ITM	Approx. Chainage	Notes
F-1-01	Pair of ruined limekilns	Meencargagh	610111, 892699	Ch. 00 (S terminus)	Depicted on 2nd ed OS
S1-AAP07	Wet area - potential for burnt mounds - north banks of stream	Dooish	610460, 892927	Ch. 00 (S terminus area)	S1-AAP07 Cappry & Dooish at lowlands immediately adjacent Burn Daurnett river network. Indicative ITM point
S1-AAP01	Area of archaeological potential	Meenacargagh, Dooish, Mullanachose, Cappry	611007, 893510	Ch. 50 Link rd	Burn Daurnett River lowlands and SW of Ballybofey. Indicative ITM point
F-1-02	Roadway	Cappry	611870, 894356	Ch. 1+500	Overgrown <i>botharín</i> lined with denuded coaxial stone walls, depicted on 1st ed OS and 2nd ed - accesses vernacular farmstead (levelled)
F-1-03	Roadway	Cappry	611818, 894340	Ch. 1+450	Overgrowth <i>botharín</i> , depicted on 1st ed OS and 2nd ed OS, accessing vernacular farmstead and forked laneway (levelled)
DLR(S&GB) Railway line	Railway line	Cappry	612409, 894923	Ch. 2+300	Fossilised remains of Stranorlar-Glenties railway line per field boundary - no associated embankments (M190)
F-1-04	Roadway	Cappry	611905, 894734	Ch. 350	<i>Botharín</i> lined with stone walls originally linking farmsteads including that of outbuilding NIAH 40907720
F-1-05	Ruined lime kiln	Ballybofey	612940, 894368	Ch. 1+550	Shown on 1st ed OS
NIAH 40907720	Outbuilding	Cappry	612106, 894673	Ch. 1+900	Two-storey stone-built outbuilding
L-129-2	Buildings	Cappry	611758, 894901	Ch. 350 Link Rd	Per LiDAR assess
Logue's Bridge	Logue's Bridge	Cappry/Ironworks	612413, 895026	Ch. 2+400	Late 19thC/early 20thC single carriageway bridge. Date plaque 'J. McKelvey 1911'
F-1-06	River access path and retaining wall on N bank of river	Ironworks	612426, 895039	Ch. 2+400	Access to river to build the bridge or remove stones/gravel from riverbed
F-1-07	Mill Race	Ironworks	612511, 895020	Ch. 2+450	Tail of mill race associated with mill at Ironworks NIAH 40907708

Ref.	Type	Townland	ITM	Approx. Chainage	Notes
F-1-08	Bridge	Ironworks/Drumboe Lower	613025, 895320	Ch. 3+025	Located just south of existing road that leads through Drumboe Demesne to the 'west gates'. This bridge corresponds with a road leading to a flax mill per 1st ed OS, crosses a stream that forms townland boundary between Ironworks and Drumboe Lower. Also a lodge marked on 1st and 2nd ed OS with a well, adjacent bridge.
F-1-10	Infilled stream (flagstone cover)	Drumboe Lower	613050, 895441	Ch. 3+100	Per landowner info (aquatic ecologist)
F-1-11	Stone field wall	Drumboe Lower	613137, 895414	Ch. 3+150	Evidence of mortar in part
F-1-12	Walled avenue	Drumboe Lower	613334, 895383	Ch. 3+300	Substantial walled avenue with fossilised building elevations in part, forming southern boundary of Abbey field
F-1-13	Cruciform plan building with outbuildings	Drumboe Lower	613316, 895380	Ch. 3+300	Indicated on 1st ed OS, south of Drumboe Abbey site. Modified by 2nd ed OS, no structural visible remains today however walling still remains at north and south sides of the c. 5m wide access avenue at this location. Cast-iron gate-post noted where the walling transitions to a single wall
F-1-14	Stone field wall	Drumboe Lower	613332, 895508	Ch. 3+375	Substantial wall forming part of western field boundary with recorded Drumboe Abbey site
F-1-15	Cross-inscribed pillar	Drumboe Lower	613331, 895483	Ch. 3+350	Inserted along western field boundary to abbey field
F-1-16	Stone field wall	Drumboe Lower	613476, 895551	Ch. 3+525	Substantial wall forming part of eastern field boundary with recorded Drumboe Abbey site
DG078-005001-	Holy Well	Drumboe Lower	613340, 895557	Ch. 3+400	Previously unlocated SMR; located in Holywell Woods, adjacent field boundary in field immediately north of Drumboe Abbey site.
DG078-005-- -	Church/Abbey 'site of'	Drumboe Lower	613388, 895442	Ch. 3+400	L123-1 ref also, and subject to geophysical survey

Ref.	Type	Townland	ITM	Approx. Chainage	Notes
S1-AP01	Possible enclosure	Ballynaglack	613515, 895915	Ch. 00 Side Rd	L123-2 ref also, and subject to geophysical survey
S1-AAP02	Area of archaeological potential	Ironworks, Drumboe Lower	613065, 895384	Ch. 3+100	SW & NE banks of River Finn incl river crossing and Drumboe Lower. Indicative ITM point
RPS 40907834	Long house	Drumboe Upper	613857, 896232	Ch. 4+400	Vernacular long-house within farm complex
S1-BH02	Poss 18th C farmstead	Drumboe Upper	613969, 896215	Ch. 4+350	Robust stone-built outbuilding with wall-mounted date plaque
L-115-1	Barrow possible	Drumboe Upper	613886, 896164	Ch. 4+250	Per LiDAR assessment
F-1-17	Raised sub-circular area	Backlees	614570, 897121	Ch. 5+400	Located on high ground north of Dunwiley fort
S1-AAP04	Area of archaeological potential	Backlees/Dunwiley	614744, 897117	Ch. 5+550	Southern slopes of ridge, well drained, good siting/vistas. Indicative ITM point
L-109-1	Barrow possible	Teevickmoy	614875, 897727	Ch. 350 Link Rd	LiDAR assess anomaly. Appears to be a natural rise in topography but nonetheless an ideal location for a ringfort/hillfort or such, given panoramic vistas. Denuded stone wall at bottom of slope to SW
F-1-19	Denuded stone wall	Teevickmoy	614858, 897683	Ch. 250 Link Rd	located southwest of L109-1 at the bottom of slope
L-110-1	Non-archaeological	Teevickmoy	615382, 897813	Ch. 6+450	This appears to be farmyard clearance (though it is more-or-less U-shaped in plan) and does not appear to be archaeological
L-106-2	Ruins of lime kiln	Teevickmoy	615349, 898077	Ch. 6+700	Overgrown remains
S1-AAP06	Wet area - potential for burnt mounds - south banks of Cloghroe River	Teevickmoy	616050, 899289	Ch. 8+150	N of Stranorlar & River Finn, rising ground at Lough Alaán to Dunwiley. Indicative ITM point
DG069-023--	Bullaun Stone	Meenavoy	615741, 899724	Ch. 50 Link rd	No obvious trace during field survey. Described as a probable bullaun stone set in rock outcrop or a large boulder by the side of a laneway. It consists of an opening, 0.2m wide and 0.2m high in the rock. At the base of this opening is a further

Ref.	Type	Townland	ITM	Approx. Chainage	Notes
					0.2m depression. The whole suggests a covered bullaun.
S1-AAP05	AAP	Mullandrait	616466, 895508	Ch. 3+450	Good quality pasture, forms part of S1-AAP05. Indicative ITM point
S1-AAP05	Good quality pasture ch. 3+320 - 1+800	Mullandrait	616463, 895925	Ch. 3+000	Elevated fields with flat platforms conducive to past settlement. Adjacent stream that forms townland boundary Treanamullin/Mullandrait. Indicative ITM point
S1-AAP05	Wet, low-lying areas	Castlebane	616525, 896542	Ch. 2+350	Unimproved pasture with hedge-lined ditches and whin scrub. This trend continues to the north of Cooladawson Road, where the unimproved, low-lying nature of some of the fields (between chainage 1350 to 1050) may suggest that some were former lakes. Indicative ITM point
F-1-21	Lime kiln	Castlebane	616154, 895993	Ch. 00 Side Rd	Ruins of lime kiln (extant) outside study area, west of ch. 1550
F-1-22	E-W bank and ditch	Castlebane	616517, 896477	Ch. 2+425	Deep drainage ditch and trackway